

Superfund Site Strategy Recommendation

Region 6

Site Name: Magnolia Road Site Site Number: TX 981 155 955Alias Site Name(s): Magnolia Road near the intersection of Telephone RoadAddress: Magnolia Road near the intersection of Telephone RoadCity/County or Parish/State/Zip: Pearland, TX (Brazoria County) 77581

Recommendation:

- ☒ 1. No further action needed; no hazardous waste problem.
- ☐ 2. No further remedial action planned under Superfund; site would not score high enough using the Hazard Ranking System to be considered for the National Priorities List.
- ☐ 3. No further remedial action planned Under Superfund; action may be appropriate under other authority: RCRA _____ NPDES _____ SPCC _____
404 _____ TSCA _____ UIC _____ SMCRA _____ State _____
Other _____
- ☐ 4. Further pre-remedial investigative action needed under Superfund:
- PA _____
SSI _____ Priority: High _____ Medium _____
LSI _____
Other _____
To be performed by _____

Discussion:

See Attachment

SUPERFUND
FILE

FEB 02 1993

REORGANIZED

Copies to (please list):

Recommended By: David Mangels G.A.-ES Date: 10/5/88Approved By: Resley B. Hatcher Date: 10-14-88

Magnolia Road Site (TXD381155955)
10/05/88

Recommendation: No further action needed: no hazardous waste problem

Discussion:

The Magnolia Road site consists of a 10 acre area alongside Magnolia Road near the intersection of Telephone road which was identified as a possible disposal location of wastes from the French Ltd. Trucking company. This site was identified by potentially responsible party (PRP) investigation of the Sikes site. However, an on-site investigation by Ecology and Environment, Inc. failed to identify any evidence of hazardous waste disposal. There was no stressed or dead vegetation, soil stains, or odors. Due to the lack of analytical or visual evidence that a hazard exists in this area, no further investigative action is needed.

D G.
10/5/88